



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor


State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed 


Report Date: 09/10/2013

Mine Name: Yerian Mine	Permit Number: S/047/0087	Mine Status: Inactive
Operator Name: Neffco Mining and MNFTG and ENG	Inspection Date: 09/04/2013	Permit Fees: Paid
Inspector(s): April Abate, Tom Nicolaysen	Inspection Time: 10:00 am	Bond Amount: \$6,000
Attendee(s):	Weather: Sunny, 90s	Bond Escalation: 09/13/2013
Inspection Purpose: Routine inspection		Prior Inspection: 04/03/2012

Conclusions and Recommendations

Division recommends approval for full bond release. The operator should fill out the form **MR-Site/Bond release** form at https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The site was inactive. No indications of trash or construction debris. No hazards to the public were observed.		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No serious drainage or erosional issues were observed.		
4. <i>Deleterious Material</i>	<input type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There are still some access roads on the site to allow access to a separate site adjacent to the reclaimed area.		
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The reclamation looked good. The hillside was graded and pocked for drainage control. There were several stockpiles of cobble sized stones observed. We weren't sure if the stockpiles belonged to the county/other entity.		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any highwalls or pits have been regraded and filled in to comply with Division standards as no remnants of such were observed.		
8. <i>Soils</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Topsoil was distributed over graded areas.		
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation is mixed with some weeds but overall it looks well developed.		
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Neffco Mining and MNFTG and ENG
11814 S Election RD
#100
Draper, UT 84020

jackstockwell@gmail.com


File: /NRLOGMFS1/OGM/GROUPS/MINERALS/WP/M047-Utah/S0470087-Yerian/inspections/09032013.pdf



One of several cobble stone stockpiles surrounding the reclaimed area.



Regraded and revegetated slope on the north end of the site.



Revegetation primarily consists of rabbit brush.



Looking from the top of the hill to the east. Rabbit brush, snake weed and other plants can be seen.